



Pipeline and Hazardous Materials Safety Administration

Office of Pipeline Safety

Bill L. Flanders

Community Assistance and Technical Services Manager



Construction & Material Quality Issues

- **Coating Issues**
- **Pipe – cutting of hot bends**
- **Pipe - wall thickness transitions and ovality**
- **Pipe & Fitting Strength – low and variable strength**
- **Welding – repairs, alignment & procedures**
- **Parallel construction**



Construction Issues

- **Coating Issues**





Construction Issues

Coating – due to pipe support





Construction Issues - Jeeping Over Soil





Coating - improper patch stick application





Coating – poor application of FBE





Coating – damaged by welding band






Coating – poor factory application



- **199 jeeps on section**



Misalignment at Segmented Bend





ADB-10-03 Girth Weld Quality Issues

- Misalignment, thickness transitions, and welding practices
- Below in-service failure occurred at 65% SMYS






Bends & Fittings

Bend fittings

Hot induction bends

- If cutting bends, use **segmentable** bends with tighter body tolerance
- Ends should meet:
 - API 5L dimensional limits
 - API 1104 fit-up requirements




Hot induction bend cross-section



Construction Issues – weld alignment

- Alignment – does it meet standards for API 1104






Construction Issues – weld alignment

- **Poor back welding & misalignment**




- **Improper ID back taper angle**







Improper Weld Transitions



ASME B31.8 Fig. I-5





Pipe Quality Issues

- Low strength X70 & X80
- Inconsistent chemical and mechanical properties
- Poor mill rolling practices
- Advisory Bulletin - ADB 09-01





Construction Issues – low strength pipe

- **Low Strength Pipe**





Construction Issues – low strength fittings



- **Several major projects have installed fittings of low strength material –**
 - **due to incorrect grade material and/or**
 - **post heat treatment**



Construction Issues – low strength fittings

- **Coating is cracking due to expansion of fitting during testing**





Construction Issues - Low Strength Fittings

**Hydrotest failure
at 80% of test
pressure**





Construction Issues – welding

- Inadequate preheat temperature





Construction Issues – welding

- **Releasing external clamp before 50% root pass is completed**





Construction Issues – welding

- **Improper low-hydrogen stick electrode storage**





Construction Issues – weld gap

- **Improper Weld Gap**






Hydrogen Cracking






Partial Thickness Repair: Only 1 Cellulosic Weld Pass






Partial Thickness Repair: Cellulosic & Low Hydrogen





Hydrogen Cracking Risk by Electrode Type

**Increasing
Risk**



E9010

E8010

E7010

E6010

} Cellulosic

FCAW (flux-cored)

E9018

E8018


E7018

GMAW (MIG)

} Low
Hydrogen



Hydrogen Cracking





Construction Issues – cracked girth weld





Recent Girth Weld Incidents





Welding Issues in Alaska

- Continuity records of the welder from the time he was tested to today
- Supports welded to piping on a DOT liquid pipeline
- Arc burn not being ground out and tested
- Low hydrogen rod not maintained per manufacturer's specifications
- Welder not welding to Pipeline operators welding procedure
- No visual inspection of welding
- No welding procedure for the material being welded



NDT issues

- Failed to meet minimum NDT requirements of 192/195
- Weld maps do not correlate to Radiographic records
- Poor radiograph technique
- Poor inspection
- NDT to ASME B31.3, not to API 1104



Construction Issues – NDE Quality

- **Poor radiographic quality**





Construction Issues

- **2nd /3rd Party Damage to Adjacent Pipeline**





Bill L. Flanders
Office of Pipeline Safety- Western Region
Community Assistance and Technical Services Manager
188 W. Northern Lights Blvd.
Suite 520
Anchorage, Alaska 99503
907-271-6518
Bill.Flanders@DOT.GOV